Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080165-1

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2951 E. COLORADO ST., PASADENA, CALIF.

No. 11893

RECEIVED FROM PLANT #9

DATE REC'D. 4-12-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322		120	0	29					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
15	732587 Bracket Strut Idler IPC 5554	15		

RECEIVED BY [signature] HMC-1069

INSPECTED BY [signature]

DATE 4-12-57

REJECTS RETURNED ON SHIP MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST. PASADENA, CALIF.

No. 11901

RECEIVED FROM PLANT #9

DATE REC'D. 4-15-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322		24		20					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
10	737778-3 Plunger IPC #5571	10		

RECEIVED BY [signature] HMC-1069

INSPECTED BY [signature]

DATE 4-15-57

REJECTS RETURNED ON SHIP MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080165-1